Date: User: Job Number First Issue **Previous Run** 

Thursday, 27/03/2008 7:35:52 AM

Linda Lacelle

**Process Sheet** 

Customer : CC-DAR01 Dart Aerospace Ltd.

: 38230 **Estimate Number** : 10804

P.O. Number

This Issue : 27/03/2008 S.O. No. :

: NC Prsht Rev.

: //

Written By

Checked & Approved By Comment

: 00015

Type

: LARGE FAB ASSY

**Drawing Name** 

: D3562-041/-042

**Part Number** : D3562041 **Drawing Number** NCR08-027

**Project Number** 

**Drawing Revision** Material

**Due Date** : 02/04/2008 Qty: 1 Um:

Each

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0 QC QUALITY CONTROL



Comment: QUALITY CONTROL

pull from stock:

D3562-041 D3562-042

2.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Comment: INSPECT WORK TO CURRENT STEP

Re-identify the D3562's correctly, using the original batch numbers.

3.0 QC5 INSPECT WORK TO CURRENT STEP



\*\*\* ENSURE BOTH PART AND BATCH #'S ARE CORRECT \*\*\*

4.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Re-package as D3562

-041 Qty:

-042 Qty:

FINAL INSPECTION/W/O RELEASE

5.0 QC21



08.04.00

Comment: FINAL IN TION/W/O RELEASE

Job Completion



08-04-01